

Turbo HD DVR V3.1.13 Release Notes



Reference NO:	PR20151202_01	
Product	Turbo HD DVR	
Classification:	Turbo nd dvk	
Date of	November 27, 2015	
Publication:		
Edit	Overseas Technical Support Dep	
Department:		

Reason of Upgrade

Fix some small bugs, so as to improve the performance of Hikvision Turbo HD DVRs and enhance customers' experience of analog surveillance system.

Firmware Updates

New Features

- i. Fix the issue that DVR will crash when choosing the PTZ protocol under the language of Russia.
- ii. Fix the issue that it will show additional tips when some E serial DVRs connect the combination signal of TVI and CVBS, while live view is normal.



Related product list:

-E Series Turbo HD DVR	DS-7104HGHI-E1、DS-7108HGHI-E1、DS-7116HGHI-E1、DS-7204HGHI-E1、DS-7208HGHI-E1、
	DS-7216HGHI-E1、DS-7208HGHI-E2、DS-7216HGHI-E2
-F Series Turbo HD DVR	DS-7104HGHI-F1、DS-7108HGHI-F1、DS-7116HGHI-F1、DS-7204HGHI-F1、DS-7208HGHI-F1、DS-7216HGHI-F1、DS-7208HGHI-F2、DS-7216HGHI-F2

Firmware version

V3.1.13 build 151127

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com