

Turbo HD DVR V3.4.4 Build160511 Release Notes (2016-5-27)

	Firmware Version:	v3.4.4 Build160511
***	SDK Version:	v5.1.6.15_build20160302
Firmware	Play Library (PlayCtrl.dll)	7.3.0.0
Basic Information	player	7.3.0.0
	Web version	V4.0.1 build 160323
	Client version	V2.04.06.06 Build20160323


Reason of Upgrade

Release V3.4.4build160511 based on 3.4.4 build160331 to support newly published model DS-7300HQHI-F4/N, DS-8100HQHI-F8/N. Fix some bugs existing in previous version, enhance products quality and meet customers' require.

Firmware Updates

New Features

- i. Newly support DS-7304/08/16HQHI-F4/N and DS-8104/08/16HQHI-F8/N.
- ii. DS-7300HQHI-F4/N, DS-8100HQHI-F8/N support POS functions.





Related product list:

	DS-7104HQHI-F1/N
	DS-7108HQHI-F1/N
	DS-7116HQHI-F1/N
	DS-7204HQHI-F1/N
-F/N Series Turbo	DS-7208HQHI-F1/N、DS-7208HQHI-F2/N
HD DVR	DS-7216HQHI-F1/N、DS-7216HQHI-F2/N
	DS-7204HUHI-F1/N、DS-7204HUHI-F2/N
	DS-7208HUHI-F1/N、DS-7208HUHI-F2/N
	DS-7304HQHI-F4/N; DS-7308HQHI-F4/N; DS-7316HQHI-F4/N
	DS-8104HQHI-F8/N; DS-8108HQHI-F8/N; DS-8116HQHI-F8/N

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com