

Turbo HD DVR V3.5.21_Build170815 Release Notes (2017-08-23)

Firmware Basic Information	Firmware Version:	V3.5.21_Build170815
	SDK Version:	V5.2.7.30 build20170428
	Play Library (PlayCtrl.dll)	7.3.2.0
	player	4.8mini
	Web version	V4.0.1 build 170419
	Client version	V2.5.8.101 build20170426

Reason of Upgrade

This version adds some new functions, modify some functions, enhance products quality and meet customers' requirements.

Modifid Functions

- i. Fixed the issue that HQHI-K series DVR reboot abnormally when enabling the Enhanced VCA mode.
- ii. Other issues fixed.

Related product list:

K Series Turbo HD DVR	DS-7204HQHI-K1、DS-7208HQHI-K1、DS-7208HQHI-K2
	DS-7216HQHI-K1、DS-7216HQHI-K2
	DS-7204HQHI-K1/P、DS-7208HQHI-K2/P、DS-7216HQHI-K2/P
	DS-7204HUHI-K1、DS-7204HUHI-K2、DS-7208HUHI-K1、DS-7208HUHI-K2、DS-7216HUHI-K2
	DS-7204HUHI-K1/P、DS-7208HUHI-K2/P
	DS-7304HQHI-K4、DS-7308HQHI-K4、DS-7316HQHI-K4

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com