

Turbo HD DVR V3.5.37 & V3.5.51 build180718 Release

Note

(2018-7-25)

Firmware Basic Information	Firmware Version	V3.5.37 build180718
	SDK Version	V5.0 build 180718
	player	4.81mini
	Play Library (PlayCtrl.dll)	7.3.5.0
	Web version	V4.0.1 build 180623
	Web version	V2.6.5.12build20171123

Reason of Upgrade

Release new K series DVR models: DS-7104HUHI-K1, DS-7108HUHI-K1.

For POC models, PoC power supply could be enabled or disabled.

For 71/72HQ and HU/HT series, all analog channels could be disabled for more IP channels access.


Note:

DS-72HUHI-K_P(DS-7204HUHI-K1/P,DS-7208HUHI-K2/P,DS-7216HUHI-K2/P) please use the firmware:


V3.5.51_Build_180718

Main Features

- i. For POC models, PoC power supply could be enabled or disabled. It's enabled as default. PoC camera can't be added to this channel when it's disabled.



- ii. For 71/72HQ and HU/HT series, all analog channels could be disabled for more IP channels access.
- iii. HQH-K model supports CVI 4MP signal access.
- iv. Hik-connect unbounding hint is newly added.



- 1) When the device has not been linked, when you press the unlink button, it will show: The device is unlinked.
- 2) Click the Link button and enter the password input interface, it will show: The device will unbind with the account
- 3) While unbounding, it will show: Unbinding device...Please wait.
- 4) If unbounding is successful, it will show: bound success.

5) if unbounding is time out, it will show: bound out time.

Modified Functions

i. Delete the video and player option when backup.

ii. Hilook Hik-connect interface Modified:

For standard firmware:

Access type is change to HiLookVision. Default address is: litedev.hilookview.com.

For neutral firmware:

Access type is changed to Guarding Vision. Default address is: litedev.guardingvision.com.

Related product list:

K Series Turbo HD DVR	V3.5.37 build180718
	DS-7104HQHI-K1、DS-7108HQHI-K1、DS-7116HQHI-K1 DS-7204HQHI-K1、DS-7208HQHI-K1、DS-7216HQHI-K1 DS-7208HQHI-K2、DS-7216HQHI-K2 DS-7204HUHI-K1、DS-7208HUHI-K1 DS-7204HUHI-K2、DS-7208HUHI-K2、DS-7216HUHI-K2 DS-7204HTHI-K1、DS-7204HTHI-K2、DS-7208HTHI-K2 DS-7304HQHI-K4、DS-7308HQHI-K4、DS-7316HQHI-K4 DS-8108HQHI-K8、DS-8116HQHI-K8 DS-7304HUHI-K4、DS-7308HUHI-K4、DS-7316HUHI-K4 DS-8108HUHI-K8、DS-8116HUHI-K8 DS-9008HUHI-K8、DS-9016HUHI-K8
	DVR-204U-F1、DVR-208U-F1、DVR-216U-F2 DS-6704HUHI-K、DS-6708HUHI-K、DS-6716HUHI-K DS-7104HUHI-K1、DS-7108HUHI-K1
	V3.5.51_Build_180718
	DS-7204HUHI-K1/P、DS-7208HUHI-K2/P、DS-7216HUHI-K2/P
	HiLook:
	DVR-204Q-K1, DVR-208Q-K1, DVR-216Q-K1 DVR-208Q-K2, DVR-216Q-K2 DVR-204U-K1,DVR-208U-K1, DVR-216U-K2 HWD-6104MH-G2, HWD-6108MH-G2, HWD-6116MH-G2 HWD-6208MH-G2, HWD-6216MH-G2 HWD-7104MH-G2, HWD-7108MH-G2, HWD-7216MH-G2

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com