V2.2.32_210929 Release Note (2021-09-29)

Device Model	DS-KD3003-E6、 DS-KD8023-E6、 DS-KD8103-E6
Firmware Version	V2.2.32_210929
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

FIX


1. Fix bugs, enhance products quality and meet customers' requirements.

V2.2.32_210812 Release Note (2021-08-12)

Device Model	DS-KD3003-E6、 DS-KD8023-E6、 DS-KD8103-E6
Firmware Version	V2.2.32_210812
iVMS-4200 Version	Late version
Hik-Connect APP	4.13.1 or above

Modify

1、 HiK-Connect is disabled and Verification code is empty by default.



FIX

1. The device does not support standard SIP and the standard SIP configuration interface has been cancelled since this version