

Android Indoor Station Firmware V2.1.78_build221209 Release Note (2022-12-09)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.78_build221209
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

Notes:

Please update firmware to the latest version to ensure the better user experience

New Feature:


1. Fix known device security vulnerability issues.

Android Indoor Station Firmware V2.1.28_210803 Release Note (2021-08-05)


Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.28_210803
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

Modify

1. Verification code is empty by default.



2. Hik-Connect Service Settings is changed to the place of Settings → Advanced Settings → Configuration → System Maintenance.



3. Fixed some bugs.

Android Indoor Station Firmware V2.1.22_210616 Release Note (2021-06-16)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.22_210616

iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

Modify

1. Optimize the compatibility with door station in protocol 1.0 firmware.
2. Solved the problem that the custom ringtone did not take effect after restarting.

Android Indoor Station Firmware V2.1.22_210525 Release Note (2021-06-03)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.16_210316
iVMS-4200 Version	3.4.0.10 Build201214
Hik-Connect APP	4.11.0.927220


New Function

1. On the basis of supporting English, French, Spanish, German, Italian, newly added

multi-language Polish, Portuguese (Brazil), Russian, Turkish, Hungarian, Dutch, Romanian, Czech, Bulgarian, Ukrainian.

2. Add Hik-Connect Service Settings in Wizard.

Wizard-Hik-Connect Service Settings 4/5



 Enable Hik-Connect Service	<input type="checkbox"/>
LBS Server	litedev.hik-connect.com
Verification Code	<input type="checkbox"/>

Previous Next Skip

Modify

1. Hik-Connect service is disabled by default for privacy protection and add Enable Switch for

verification code display in Hik-Connect Server Settings.



Android Indoor Station Firmware V2.1.16_210316 Release Note (2021-03-18)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
--------------	--------------------------------

Firmware Version	Android Indoor Station : V2.1.16_210316
iVMS-4200 Version	3.4.0.10 Build201214
Hik-Connect APP	4.11.0.927220

New Function

1. Repair the custom ringtone failure after restart.

Modify