

## Android Indoor Station Firmware V2.1.78\_build230204 Release Note (2023-02-24)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.78_build230204
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

**Notes:**

Please update firmware to the latest version to ensure the better user experience

**New Feature:**

1. Online update firmware of alarm/IPC devices inside Hik-Connect App.

**Modified feature:**

1. Optimize Wi-Fi function and device will scan every 30s in the background when the screen is off.

## Android Indoor Station Firmware V2.1.78\_build221209 Release Note (2022-12-09)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.78_build221209
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

**Notes:**

Please update firmware to the latest version to ensure the better user experience

**New Feature:**


2. Fix known device security vulnerability issues.

## Android Indoor Station Firmware V2.1.28\_210803 Release Note (2021-08-05)


Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.28_210803
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

### Modify

1. Verification code is empty by default.



2. Hik-Connect Service Settings is changed to the place of Settings → Advanced Settings → Configuration → System Maintenance.



3. Fixed some bugs.

## Android Indoor Station Firmware V2.1.22\_210616 Release Note (2021-06-16)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.22_210616
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

### Modify

1. Optimize the compatibility with door station in protocol 1.0 firmware.
2. Solved the problem that the custom ringtone did not take effect after restarting.

## Android Indoor Station Firmware V2.1.22\_210525 Release Note (2021-06-03)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.16_210316

iVMS-4200 Version	3.4.0.10 Build201214
Hik-Connect APP	4.11.0.927220

## New Function

1. On the basis of supporting English, French, Spanish, German, Italian, newly added

multi-language Polish, Portuguese (Brazil), Russian, Turkish, Hungarian, Dutch, Romanian, Czech, Bulgarian, Ukrainian.

2. Add Hik-Connect Service Settings in Wizard.

### Wizard-Hik-Connect Service Settings 4/5

Enable Hik-Connect Service

---

LBS Server litedev.hik-connect.com

---

Verification Code

---

Previous Next Skip

## Modify

1. Hik-Connect service is disabled by default for privacy protection and add Enable Switch for verification code display in Hik-Connect Server Settings.

### Hik-Connect Server Settings

Cloud Service

---

LBS litedev.hik-connectru.com

---

Verification Code

---

Hik-Connect Server Status Disconnected

---



< Hik-Connect Server Settings

Cloud Service

LBS litedev.hik-connectru.com

Verification Code 7a

Hik-Connect Server Status Disconnected



## Android Indoor Station Firmware V2.1.16\_210316 Release Note (2021-03-18)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.16_210316
iVMS-4200 Version	3.4.0.10 Build201214
Hik-Connect APP	4.11.0.927220

### New Function

1. Repair the custom ringtone failure after restart.

### Modify