

-I Series NVR V3.3.6 Release Notes



Reference NO:	20150910_01			
Product Classification:	DS-7600NI-I2(/8P)(/16P)			
	DS-7700NI-I4(/16P)			
	DS-9600NI-18			
Date of	August 28, 2015			
Publication:	August 28, 2015			
Date of	August 29, 2015			
Change:	August 28, 2015			

Reason of Upgrade

To fix some small bugs existing on previous firmware versions, so as to improve the performance of Hikvision -I series NVRs and enhance the experience of network surveillance system.

Firmware Updates

Add a configuration option "Enable H.265 (For Initial Access)", which is used for switching stream to
 H.265 automatically when NVR accesses IPC at first time.

		Ca	mera Manag	ement					
- Camera >	IP Camera	IP Camera Impo	ort/Export						
⊯r osd		dd/De Status	Security			Up	Camera N	ame Protoco	^
🖏 Image		• – • –	 Active Active 	10.6.38		-	-	HIKVIS HIKVIS	
- 0		- D -	Active	10.6.38		-	-	HIKVIS	
S PTZ	(∍ –	Active	10.6.38	.202 📑	-	-	HIKVIS	
★ Motion		• –	Active	10.6.38		-	-	HIKVIS	-
Privacy Mask		• – • •	 Active Active 	10.6.38		-	-	HIKVIS HIKVIS	
👋 Video Tamper	(•	Active	10.6.38	.200 📝	-	-	HIKVIS	
Video Loss	(•	Active	10.6.38		-	-	HIKVIS	
C VCA NEW	(• •	 Active 	192.168	3.254.8 📝	-	-	HIKVIS	~
	Refres	h One-touch	A Upgr	ade	Delete	One	-touch A	Custom Add	ii
	Enable H.2	265 (For Initial Access)							
★ Live View Net Receive Idle Bandwidth: 320Mbps					Back				



- ii. Change the incoming/outgoing bandwidth of DS-7600NI-I2 and DS-7700NI-I4. The incoming bandwidth of 32-ch is changed from 320Mbps to 256Mbps, and the outgoing bandwidth is changed to 256Mbps for all types.
- iii. Fix the issue of virtual host enabling failure after disabling it for the first time.
- iv. Fix the issue of single channel/all channels live view switch failure for channel-zero in iVMS-4200.
- v. Fix the issue of menu display abnormality when resolution is greater than 1080p with HDMI as aux output for DS-7600NI-I2 and DS-7700NI-I4.
- vi. Fix the issue of no audio in live view with G.722 audio format in iVMS-4500.
- vii. Fix the issue of PTZ cameras with motorized lens operation failure.



First Choice for Security Professionals

Related product list:

	DS-9632NI-I8 DS -9664NI-I8
-I Series NVR	DS-7716NI-I4(/16P) DS-7732NI-I4(/16P)
	DS-7608NI-I2(/8P) DS-7616NI-I2(/16P)

Firmware version

V3.3.6, build 150828

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after

upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com