

Fingerprint Terminal V1.4.0_build230403

Release Note (2023-06-14)

Device Model	Firmware
DS-K1T804AF/AMF/AEF	ACS_1T804A_J1_EN_STD_V1.4.0_build230403
DS-K1T804BF/BMF/BEF	ACS_1T804B_J1_EN_STD_V1.4.0_build230403
DS-K1A802AF/AMF/AEF	ACS_1A802A_J1_EN_STD_V1.4.0_build230403
DS-K1T8003 Series	ACS_1T8000_J1_EN_STD_V1.4.0_build230403
DS-K1A8503 Series	ACS_1A8500_J1_EN_STD_V1.4.0_build230403

Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Modified Features

1. Fixed known security vulnerabilities

for details, please refer:

<https://www.hikvision.com/en/support/cybersecurity/security-advisory/security-vulnerability-in-some-hikvision-access-control-intercom/>

Fingerprint Terminal V1.4.0_build220523

Release Note (2022-05-25)


Device Model	Firmware
DS-K1T804AF/AMF/AEF	ACS_1T804A_J1_EN_STD_V1.4.0_build220523
DS-K1T804BF/BMF/BEF	ACS_1T804B_J1_EN_STD_V1.4.0_build220523
DS-K1A802AF/AMF/AEF	ACS_1A802A_J1_EN_STD_V1.4.0_build220523
DS-K1T8003 Series	ACS_1T8000_J1_EN_STD_V1.4.0_build220523
DS-K1A8503 Series	ACS_1A8500_J1_EN_STD_V1.4.0_build220523

Reason of Upgrade



Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Modified Features


1. ID support letter, ID length less than 32 digit



2. Support ID, name desensitization function



3. Support Hik-connect account unlinking function



Fingerprint Terminal V1.3.37_build210802 Release Note (2021-09-09)


Device Model	Firmware
DS-K1T804AF/AMF/AEF	ACS_1T804A_MCU_J1_EN_STD_V1.3.37_build210802
DS-K1T804BF/BMF/BEF	ACS_1T804B_J1_EN_STD_V1.3.38_build210802
DS-K1A802AF/AMF/AEF	ACS_1A802A_J1_EN_STD_V1.3.37_build210802
DS-K1T8003 Series	ACS_1T8000_J1_EN_GM_V1.2.3_build191120
DS-K1A8503 Series	ACS_1A8500_J1_EN_STD_V1.3.37_build210802

Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Modified Features

4. Add Hik-Connect menu in device UI Menu→Comm→Mobile App. The function is disabled in default. (For DS-K1T804A, DS-K1T804B, DS-K1T8003 only)



Fingerprint Terminal V1.2.3_build191120 Release Note (2019-11-16)

Device Model	Firmware
DS-K1T804F/MF/EF	ACS_1T804_M0_EN_GM_V1.2.3_build191120
DS-K1A802 F/MF/EF	ACS_1A802_J1_EN_GM_V1.2.3_build191120
DS-K1T8003 Series	ACS_1T8000_J1_EN_GM_V1.2.3_build191120
DS-K1A8503 Series	ACS_1A8500_J1_EN_GM_V1.2.3_build191120

NOTE:

If you upgrade **ARM** firmware from **v1.1.x** .

Don't reboot device directly!

Choose **restore all** after upgrade.

This is because new firmware's data structure is not compatible with old firmware. Rebooting directly will lead to device crash. It is recommend to upload all the old data to client software (iVMS4200) before upgrade, and apply all data to device again when upgrade finish.

If you upgrade from firmware 1.2.x, you can directly reboot the device.

Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Improved Features

1. Improve the compatibility with Hik-Central Professional platform software.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com