## **AX PRO**

# Version: V1.2.9

**Release Note** 

## (2024-04-15)

### 1. Firmware Basic Information

Firmware	Firmware Version	V1.2.9_build240412
Basic		DS-PWA48-E-WB
Information	Device Type	DS-PWA64-L-WE/WB/WE(RU) DS-PWA96-M-WE/WB/WE(RU)
mormation	51	DS-PWA96-M2-WE/WB
		DS-PWA96-M2H-WE/WB/WE(RU)

#### Notes:

1. Please update firmware to the latest version to ensure the perfect user experience.

2. For installers, it is recommended to install and maintain devices via Hik-Partnerpro.

# 2. V1.2.9 Upgrade Note

#### 2.1 Battery charging function optimization


When the temperature rises, the panel battery can only start charging at about 5°C before the modification, and after the optimization, the panel battery can now start charging at 2°C.

Notice: Hardware version needs to be update.


- 2.2 Fix the problem of non-compliance of PD6662 standard function.
- 2.3 Support the following devices DS-PT1-WE/WB)(B), DS-PDMCK-EG2-WE/WB(B), DS-PR1-WE/WB(B) access.
- 2.4 Support HIK IoT card.
- 2.5 HPP sharing function optimization.

Modify authorization permissions, default arm and disarm/Silence alarm

permissions aren't granted to HPP (installer), but still support HC (end user) to manually tick. Permissions remain unchanged in the rest of the cases.



2.6 Sounder& transmitter's original AC Power Loss notification modified to Expander External Power Failure.




# HIKVISION AX PRO V1.2.9 Release Notes

Expander AC Po	ower Loss	. () Expander Exter	nal Power Failure 🛛 🔨
0		3	- [
Time Source Peripheral Device Event Type	Today 171022 (CAX PRO TSPB) Multi Transmitter 1 Exception	Time Source Peripheral Device Event Type	AXTRO ISP(B) Multi Transmitter 1 Exception

Before

After

Detector's original AC Power Loss notification modified to Detector External Power Failure.



Before

After

#### <u>Remarks:</u>

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

• Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com