IP Video Intercom Firmware
Version: V1.4.5
Release Note (2017-09-21)

Firmware Basic Information	Firmware Version:	V1.4.5 Build 170921
	iVMS-4200	Version V2.6.2.50 build 20170724 (Customized version based on baseline V2.6.2.6)

Note: Intercom firmware V1.4.5 build 20170921 needs iVMS-4200 V2.6.2.50 build 20170724

1. New Features

- <u>Support for 4 languages – English, Spanish, Portuguese and Czech</u>.

 Note: After the upgrade, language in the devices can be changed via iVMS4200 in <u>Remote configuration->System Maintenance.</u>

2. Improved Features

- Improved compatibility with indoor stations running 1.4.71 firmware.

3. Bug fixes

- Fixed indoor station audio button in live view not working when connected to DS-KB8112-IM

Supported Product List		
Product Category	Model Number	Product Description
IP Video Intercom	DS-KD8102-V	Vandal-Resistant Villa Door Station

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the date of change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.

- Product design and specifications are subject to change without prior notice.

- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

- Hikvision is not liable for any typing or printing errors.