Turbo HD DVR V3.4.3 Release Notes
(2016-2-24)

Firmware Basic Information	Firmware Version:	v3.4.3 build150203
	SDK Version:	v5.1.6.5(20160112)
	Play Library (PlayCtrl.dll)	7.3.0.0
	player	6.0.0.4
	Web version	V4.0.1 build160128
	Client version	V2.4.4.1 build20160129

Reason of Upgrade

Newly support 3MP & 5MP TVI camera access, fix some bugs existing on previous firmware versions, enrich

the product models for different requirements. This version newly supports DS-7100HGHI-F1/N,

DS-7200HGHI-F1/N, DS-7200HUHI-Fx/N models.

Firmware Updates
New Features

i.   Newly support 3MP & 5MP TVI camera access for model DS-7200HUHI-Fx/N. DS-7204/08HUHI-Fx/N
       support 4/8-ch 3MP@15fps camera access, DS-7208HUHI-Fx/N support 2-ch 5MP@12fps camera access
       (only for 1st and 5th channels).

ii.   DS-7208HUHI-Fx/N support 4K (3840x2160)/30HZ & 2K(2560x1440)/60HZ HDMI output.

iii.   DS-7200HUHI-Fx/N support 2-ch 4MP IPC access.

Related product list:

-F/N Series Turbo HD DVR	DS-7204HUHI-F1/N
	DS-7204HUHI-F2/N
	DS-7208HUHI-F1/N
	DS-7208HUHI-F2/N

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after

upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

> Note:
> - Hikvision has all rights to alter, modify and cancel this notice.
> - Hikvision doesn't give any guarantee for old models' stock.
> - Hikvision is not liable for any typing or printing errors.
> - For special model's change details, please contact our local technical support team.