# Conventional SD DVR V3.1.6_build170613 Release Notes (2017-06-16)

Reason of Upgrade

Conventional SD DVR deletes Hiddns and IP Server function, newly support Hik-Connect. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Main Features

i.   Delete HiDDNS and IPServer access. Available DDNS access includes DynDns, PeanutHall, NO-IP.

ii.   Newly support Hik-Connect(HC) function, support HC functions like playback, live view and alarm push. HC function is not enabled by default.

iii.   Support HC domain name service.

iv.   Fixed the issue that device crash when dragging the progress bar on playback page of web.

v.   Support TLS encryption email.

vi.   Fixed the issue that coaxial control of 9th channel failed.

Related product list:

Conventional SD DVR	DS-7204HVI-SV、DS-7208HVI-SV、DS-7216HVI-SV、DS-7204HFI-SH、DS-7208HFI-SH、DS-7216HFI-SH、DS-7204HWI-SH、DS-7208HWI-SH、DS-7216HWI-SH、DS-7208HWI-SL、DS-7216HWI-SL、DS-7304HFI-SH、DS-7308HFI-SH、DS-7316HFI-SH、DS-7304HWI-SH、DS-7308HWI-SH、DS-7316HWI-SH、DS-7224HVI-SH、DS-7232HVI-SH、DS-7224HWI-SH、DS-7324HI-SH、DS-7332HI-SH、DS-7324HFI-SH、DS-7332HFI-SH、DS-7324HWI-SH、DS-7332HWI-SH、DS-8124HCI-SH、DS-8132HCI-SH、DS-8124HFSI-SH、DS-8132HFSI-SH、DS-8124HWSI-SH、DS-8132HWSI-SH、DS-7204HWI-E1、DS-7208HWI-E2、DS-7216HWI-E2、DS-7208HWI-E1、DS-7216HWI-E1、DS-7204HWI-E1/C、DS-7208HWI-E2/C、DS-7216HWI-E2/C、DS-7304HWI-E4/C、DS-7308HWI-E4/C、DS-7316HWI-E4/C、DS-7224HWI-E2、DS-8104HWI-E4/C、DS-8108HWI-E8/C、DS-8116HWI-E8/C

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after

upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

> Note:
> - Hikvision has all rights to alter, modify and cancel this notice.
> - Hikvision doesn't give any guarantee for old models' stock.
> - Hikvision is not liable for any typing or printing errors.
> - For special model's change details, please contact our local technical support team.