

Turbo HD DVR V3.4.83_build170526 Release Notes (2016-06-06)

Firmware Basic Information	Firmware Version:	V3.4.83_build170526
	SDK Version:	V5.2.6.25_build20170104
	Play Library (PlayCtrl.dll)	6.0.0.4
	player	7.3.2.63
	Web version	V4.0.1 build 170118
	Client version	V2.05.06.07 build20170210

Reason of Upgrade

Fix some issues. This version is only suitable for DS-71/7200HGHI-Fx, DS-71/72/73/8100HQHI-Fx/N, DS-72/73/76/81/9000HUHI-Fx/N. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Main update

Modified functions

- i. Fixed the issue that controlling device by remote control failed when device number of unit was from 100 to 254.
- ii. Other issues fixed.

Related product list:

-F/N Series Turbo HD DVR	DS-7104HQHI-F1/N、DS-7108HQHI-F1/N、DS-7116HQHI-F1/N
	DS-7204HQHI-F1/N、DS-7208HQHI-F1/N、DS-7208HQHI-F2/N
	DS-7216HQHI-F1/N、DS-7216HQHI-F2/N
	DS-7304HQHI-F4/N、DS-7308HQHI-F4/N、DS-7316HQHI-F4/N
	DS-8104HQHI-F8/N、DS-8108HQHI-F8/N、DS-8116HQHI-F8/N
	DS-7104HGHI-F1、DS-7108HGHI-F1、DS-7116HGHI-F1
	DS-7204HGHI-F1、DS-7208HGHI-F1、DS-7208HGHI-F2
	DS-7216HGHI-F1、DS-7216HGHI-F2
	DS-7204HUHI-F1/N、DS-7208HUHI-F1/N、DS-7208HUHI-F2/N
	DS-7216HUHI-F1/N、DS-7216HUHI-F2/N
	DS-7604HUHI-F1/N、DS-7608HUHI-F2/N、DS-7216HUHI-F2/N
	DS-7304HUHI-F4/N、DS-7308HUHI-F4/N、DS-7316HUHI-F4/N
	DS-8104HUHI-F8/N、DS-8108HUHI-F8/N、DS-8116HUHI-F8/N
	DS-9004HUHI-F8/N、DS-9008HUHI-F8/N、DS-9016HUHI-F8/N

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.