

Network Video Recorder Version: V3.6.22 build170629 Release Note

(2017-7-5)

	Firmware Version:	V3.6.22 build170629
Firmware	SDK Version:	V5.2.5.25 build160923
	ONVIF Protocol:	ONVIF V2.4.0
Basic Information	IVMS-4200:	V2.5.3.12 build20161020
	Web Component:	V4.0.1 build 160923

Reason of Upgrade

Optimize NVR's stability and performance.

Firmware Upgrade Optimize

1. [Radiator]

Optimize NVR's radiator performance after running a long time by increasing fan speed.

2. [IP camera access]

Optimize NVR's compatibility with Hikvision H265 IP camera (DS-2CD2xx5).

3. [System]

Optimize NVR's stability after connecting to client like IVMS-4200 and IVMS-5200.



Supported Product List

Super NVR	DS-96128(256) NI-I16/H	DS-96128(256) NI-I24/H
	DS-96128(256) NI-I16	DS-96128(256) NI-I16

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect

automatically after upgrading from previous versions. We'd like to inform you the above

changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this

action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.