

PTZ Camera Firmware Version: V5.5.810

Release Note

(2021-12-17)

Firmware Version Information

For iDS-2SK7184MXS-D(C5F2)(O-STD)(T2)

IPDZLFS_H5_EN_STD_5.5.810_211126

Please refer to the table below to get specific model

Camera Features

1. New Features

N/A

2. Improved Features

- Fix security issue in ISAPI

3. Leftover Issues

N/A

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.



First Choice for Security Professionals

- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou
310051, China

Tel: +86-571-8807-5998

Supported Product List	
Product Category	Model Number
360° smart-linkage PTZ	iDS-2SK7184MXS-D(C5F2)(O-STD)(T2)

Note: Models in red font are newly released models.