

A8 AcuSense NVR V4.61.010_220606

Release Notes

(2022-6-10)

Firmware Basic Information	Firmware Version:	V4.61.010_220606
	SDK Version:	V6.1.7.20_build20210513
	Play Library (PlayCtrl.dll)	V6.0.0.5
	Web version	V4.5.0 build 211229
	Client version	V3.6.5.4 build20210929

Reason of Upgrade

Optimize product performance.

Solved issue

1. Fixed the black screen issue of zero channel live view after the CVBS device is enabled
2. Fixed issue of remote live viewing multi-slice camera encrypted stream on NVR will appear slow, green screen, after NVR open code stream encryption.
3. Fixed issue of smart module probability not starting.

Related product list

AcuSense NVR	Overseas:
	DS-9616NXI-I8/S(C)
	DS-9632NXI-I8/S(C)
	DS-9664NXI-I8/S(C)
	DS-7916NXI-I4/S(C)
	DS-7932NXI-I4/S(C)
	DS-7916NXI-I4/16P/S(C)
	DS-7932NXI-I4/16P/S(C)
	DS-7808NXI-I2/S(C)
	DS-7816NXI-I2/S(C)
	DS-7808NXI-I2/8P/S(C)

	DS-7816NXI-I2/16P/S(C)
	DS-7716NXI-I4/S(C)
	DS-7732NXI-I4/S(C)
	DS-7716NXI-I4/16P/S(C)
	DS-7732NXI-I4/16P/S(C)
	DS-7608NXI-I2/S(C)
	DS-7616NXI-I2/S(C)
	DS-7608NXI-I2/8P/S(C)
	DS-7616NXI-I2/16P/S(C)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com