

Turbo HD DVR V4.30.101 build191120

Release Note

Firmware Basic Information V4.21.000 build 190722	Firmware Version:	V4.30.101 build191120
	SDK Version:	V6.0.2.5_build20190105
	Onvif Version:	V2.2
	Player:	4.81mini
	Play Library (PlayCtrl.dll)	7.3.5.0
	Web component:	V4.0.1 build 190920
	IVMS-4200:	2.7.1.51

Reason of Upgrade:

- Release Coaxial-audio models.
- Add new requirements and optimize product performance.

New features:

1. 【Release Coaxial-audio models】

1) New coaxial audio models are released. Check “Released product list” for details.


Models that support coaxial-audio, you can see the word “(S)” in the expanded information section of the label.



2. 【Support Coaxial-audio】

Audio supports coaxial transmission. The default audio source is coaxial audio.

If the channel supports local audio, user can select “local” in the drop-down box.



3. 【support new functions of Hik-Connect】

1) Support video download and multiple speed playback in Hik-connect.

- 2) Support one-key alarm linkage and “Don’t disturb mode” in Hik-Connect.

4. 【Support Sound & Light alarm】

Support configuring the linkage of event with sound & light alarm in DVR.

Normal Linkage	Trigger Alarm Output	Trigger Channel	PTZ Linkage
<input checked="" type="checkbox"/> Full Screen Monitor	<input checked="" type="checkbox"/> CAM1->1(Light)	<input checked="" type="checkbox"/> A1	PTZ Linkage [A1] Carr -
<input checked="" type="checkbox"/> Audible Warning	<input checked="" type="checkbox"/> CAM1->2(Alarm Out)	<input type="checkbox"/> A2	<input type="radio"/> Preset No. 1 -
<input checked="" type="checkbox"/> Notify Surveillance	<input checked="" type="checkbox"/> CAM1->3(Sound)	<input type="checkbox"/> A3	<input type="radio"/> Patrol No. 1 -
<input checked="" type="checkbox"/> Send Email		<input type="checkbox"/> A4	<input type="radio"/> Pattern No. 1 -
<input checked="" type="checkbox"/> Upload Captured P...	<input checked="" type="checkbox"/> Local->1		

5. 【New Interface for Easy Mode】

NTP synchronization service configuration added to system configuration interface.

6. 【New Interface for Expert Mode】

- 1) Add DDNS configuration page in network configuration.
- 2) Add a port mapping configuration page in the network configuration.

Modified Functions

1. 【Function optimization】

- 1) Wizard interface optimization.
- 2) Interface visual optimization.
- 3) Optimization of interface usability.

Released product list:

-HGH	DS-7232HGHI-K2	DS-7216HGHI-K1(S)
	DS-7204HGHI-F1(S)/L	DS-7216HGHI-K2(S)
	DS-7204HGHI-F1(S)	DS-7104HGHI-F1(S)
	DS-7208HGHI-F1/N(S)	DS-7108HGHI-F1/N(S)/L
	DS-7108HGHI-F1/N(S)	DS-7104HGHI-F1(S)/L
	DS-7208HGHI-F1/N(S)/L	DS-7116HGHI-K1(S)
	DS-7224HGHI-K2	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: techsupport@hikvision.com