

Turbo HD DVR V3.5.22 Build170927 Release Notes (2017-09-30)

Firmware Basic Information	Firmware Version:	V3.5.22 Build170927
	SDK Version:	V5.2.7.30 build20170428
	Play Library (PlayCtrl.dll)	7.3.2.0
	player	4.8mini
	Web version	V4.0.1 build 170419
	Client version	V2.5.8.101 build20170426

Reason of Upgrade

Regarding customers' usage habit and market new demand of PoC functions, Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Main Features

i. Update of PoC connection Capacity

1. Enhance the max PoC connection capacity from all channels AF to all channels AT cameras.

Device	Past	Now
4-ch device	Support 4-ch AF cameras	Support 4-ch AT cameras
8-ch device	Support 8-ch AF cameras	Support 8-ch AT cameras
16-ch device	Support 16-ch AF cameras	Support 8-ch AT +8-ch AF cameras Or up to 12-ch AT access

For 16-ch device, support hybrid access of AT and AF camera as followings:

AT camera access	12	11	10	9	8	N (0~7)
AF camera access	0	2	4	6	8	16-N

2. Newly support prompt on live view when there are not enough power supply for PoC cameras connected

09-20-2017 Wed 22:51:09

Insufficient Power For PoC

NO VIDEO

Camera 13

- ii. Other functions modified

Related product list:

K Series Turbo HD DVR	DS-7108HQHI-K1
	DS-7204HQHI-K1
	DS-7208HQHI-K1、DS-7208HQHI-K2
	DS-7216HQHI-K1、DS-7216HQHI-K2
	DS-7204HQHI-K1/P、DS-7208HQHI-K2/P、DS-7216HQHI-K2/P
	DS-7204HUHI-K1、DS-7204HUHI-K2、DS-7208HUHI-K1、DS-7208HUHI-K2、DS-7216HUHI-K2
	DS-7204HUHI-K1/P、DS-7208HUHI-K2/P
DS-7304HQHI-K4、DS-7308HQHI-K4、DS-7316HQHI-K4	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com