

Test Report No.: **1160042977a 002**

Page 1 of 34

Client: Hangzhou Hikvision Digital Technology Co., Ltd.
No.555 Qianmo Road, Binjiang District Hangzhou 310052, China

Test item(s): Color camera

Test Model No(s): DS-2CE56H0T-IRMMF, DS-2CE56H0T-ITPF,
DS-2CE56H0T-ITMF, DS-2CE56H0T-IT3F,
DS-2CE56H0T-VPITF

Reference Style No(s). DS-2CE56D1T-IRP, DS-2CE56D0T-IRP, DS-2CE56H0T-IT1F

Sample Receiving date: 2017-12-04, 2018-01-24

Delivery condition: Apparent good, Samples tested as received

Test specification:

Test result:

Overall results according to tests performed

1. Cadmium, Lead, Chromium (VI), Mercury, Polybrominated biphenyls (PBB) and Polybrominated diphenyl ethers (PBDE) Benzylbutyl phthalate (BBP), Dibutyl phthalate (DBP), Bis(2-ethylhexyl) phthalate (DEHP), Diisobutyl phthalate (DIBP) According to RoHS (recast): Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment, 2011/65/EU last amended by (EU) 2015/863

PASS

Other Information:

Test period: 2017-12-04 ~ 2018-01-05, 2018-01-25 ~ 2018-01-30

Please be kindly informed that all the content recorded in captioned report 1160042977a 001 issued on Jan.31, 2018 is cancelled and now superseded by 1160042977a 002.

The testing items in the report were subcontracted to the lab which complied with ISO17025.

For and on behalf of
TÜV Rheinland / CCIC (Ningbo) Co., Ltd.

2018-02-07 Xie Xianqiang Department Manager
Date Name/Position



The stamp is rectangular with a double border. The top text reads 'Geprüft und Genehmigt (Reviewed and approved)'. Below this is a handwritten signature in black ink. At the bottom of the stamp, it says 'TÜV Rheinland Group'. To the left of the signature is a small logo consisting of a triangle with a circle inside, and the letters 'TUV' below it.

Test result is drawn according to the kind and extent of tests performed.
This test report relates to the a. m. test sample. Without permission of the test center this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any safety mark on this or similar products.