### **DS-K1T320** Series Access Control Terminal

### **Release Notes (2023-06-14)**

Device Model: DS-K1T320MFWX , DS-K1T320MFX, DS-K1T320MWX , DS-K1T320MX DS-K1T320EFWX, DS-K1T320EFX	Firmware Version	ACS_320_F2pro_EN_STD_V3.5.0_build230531 ACS_320_F2pro_EN_NEU_V3.5.0_build220531		
DS-K1T320EWX, DS-K1T320EX		HikCentral AC:		
Naming Rule: M for Mifare card, E for EM card F for Fingerprint, W for Wi-Fi	Software	https://www.hikvision.com/en/support/download/s oftware/hikcentral-access-control-v2-0-1/		

### **Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

1. Fixed known security vulnerabilities for details, please refer: <u>https://www.hikvision.com/en/support/cybersecurity/security-advisory/security-vulnerability-in-some-hikvision-access-control-intercom/</u>

# DS-K1T320 Series Access Control Terminal Release Notes (2022-08-15)

<b>Device Model:</b> DS-K1T320MFWX , DS-K1T320MFX, DS-K1T320MWX , DS-K1T320MX	Firmware Version	ACS_320_F2pro_EN_STD_V3.5.0_build220706 ACS_320_F2pro_EN_NEU_V3.5.0_build220706		
DS-K1T320EFWX, DS-K1T320EFX		HikCentral AC:		
DS-K1T320EWX, DS-K1T320EX		https://www.hikvision.com/en/support/download/s		
	C - 6	oftware/hikcentral-access-control-v1-3-0/		
Naming Rule:	Software	iVMS:		
M for Mifare card, E for EM card		https://www.hikvision.com/en/support/download/s		
F for Fingerprint, W for Wi-Fi		oftware/ivms4200-series/		

### **Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

2. Optimize the automated test process of the production line to solve the problem of stuck in the key test process

## DS-K1T320 Series Access Control Terminal Release Notes (2022-08-15)

Device Model: DS-K1T320MFWX , DS-K1T320MFX, DS-K1T320MWX , DS-K1T320MX	Firmware Version	ACS_320_F2pro_EN_STD_V3.5.0_build220706 ACS_320_F2pro_EN_NEU_V3.5.0_build220706
DS-K1T320EFWX, DS-K1T320EFX DS-K1T320EWX, DS-K1T320EX		HikCentral AC: https://www.hikvision.com/en/support/download/s
Naming Rule: M for Mifare card, E for EM card F for Fingerprint, W for Wi-Fi	Software	oftware/hikcentral-access-control-v1-3-0/ iVMS: https://www.hikvision.com/en/support/download/s oftware/ivms4200-series/

### **Reason of Upgrade**

New model DS-K1T320 series access control terminals first time released.





Model	Card	Fingerprint	Face	Wi-Fi	Event
DS-K1T320MFWX	1.000	1.000		Support	100,000
DS-K1T320MFX	- 1,000	1,000		N/A	
DS-K1T320MWX	(Mifare 1		500	Support	
DS-K1T320MX	card)	N/A		N/A	
DS-K1T320EFWX	1,000 (EM card)	1 000		Support	
DS-K1T320EFX		1,000		N/A	
DS-K1T320EWX		NT/A		Support	
DS-K1T320EX		N/A		N/A	

### **New Features**


- 1. 2.4 inch LCD screen with 2MP lens, white light supplement, physical keypad.
- 2. Easy to manage: Local interface, PC web and mobile web
- 3. Abundant authentication modes, including face, fingerprint, card, PIN code, etc. (varies according to different models), and PIN code must be configured from iVMS or HikCentral software.
- 4. Multiple language: English, Español, العربية, ภาษาไทย, Indonesian, русский, Vietnamese, Português Brasileiro, 한국어, 日本語
- 5. Wall mount or desktop placement (desktop stand should be ordered separately)
- 6. Capacity
- 7. **ISAPI** protocol makes it easier to integrate with third-party software;
- 8. Support ISUP 5.0(EHome 5.0) protocol to manage devices located in different location;
- 9. Remote lock control via the Hik-Connect mobile app

#### 10. Network

Support TCP/IP and Wi-Fi, adapt to LAN (network) or WAN (ISUP 5.0) network environment

### 11. Function

a. Brand new UI interface for PC web and mobile web



Note: For mobile web, device and mobile phone Wi-Fi should be in same network.



- b. Self-defined text prompt for verification success or failed
- c. Self-defined UI standby picture
- d. Buzzer prompt for door opening

### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com