

DS-K1T331 Series MinMoe Terminal Release Notes (2022-03-09)

Device Model: DS-K1T331 DS-K1T331W	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build220210 ACS_331_AI2_EN_NEU_V3.2.30_build220210
	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

1. Fix the problem that the occasional screen backlight cannot be turned off;

DS-K1T331 Series MinMoe Terminal Release Notes (2022-02-09)

Device Model: DS-K1T331 DS-K1T331W	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build211229 ACS_331_AI2_EN_NEU_V3.2.30_build211229
	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

2. Fix the issue that the device events exceeds the capability set and the automatic deletion cannot be fully covered;

DS-K1T331 Series MinMoe Terminal Release Notes (2021-11-15)

Device Model: DS-K1T331 DS-K1T331W	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build211110 ACS_331_AI2_EN_NEU_V3.2.30_build211110
	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

1. Fix the device offline issue caused by searching device event from iVMS4200 client through ISUP5.0 protocol;
2. Fixed some issues about ISAPI protocol.
3. Optimize the connection with HikCentral Professional platform;


DS-K1T331 Series MinMoe Terminal Release Notes (2021-10-18)

Device Model: DS-K1T331 DS-K1T331W	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build210731 ACS_331_AI2_EN_NEU_V3.2.30_build210731
	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Add new function, fix bugs, enhance products quality and meet customers' requirements.


New Features

1. Add Hik-Connect menu in device UI Menu → Comm. The function is disabled in default.



Modified Features

1. Optimize the wake-up distance of the device screen through the face, and the wake-up distance is consistent with the recognition distance



DS-K1T331 Series MinMoe Terminal Release Notes (2021-06-23)

Device Model: DS-K1T331 DS-K1T331W	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build210609 ACS_331_AI2_EN_NEU_V3.2.30_build210609
	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

2. Optimize the function of exporting data to U disk.
3. Optimize the working mechanism of infrared supplement light.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com