

## Access Control Terminal K1T802 V2.0.4\_build211028 Release Notes

<b>Device Model:</b> DS-K1T802E DS-K1T802M	Firmware Version	V2.0.4_build20211028
	4200 Version	Latest version

### Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

### Modified Feature

1. Optimize the card synchronization process with platform
2. Fix the problem that the host time occasionally becomes 2036 after the NTP time calibration is turned on;

## Access Control Terminal K1T802 V2.0.3\_build190306 Release Notes

<b>Device Model:</b> DS-K1T802E DS-K1T802M	Firmware Version	V2.0.3_build190306
	4200 Version	V2.6.5.6 build20171016

### Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

### Bugs Fix

3. Fix a bug that incidental uploading illegal value when upload event;
4. Fix a bug about open door timeout logic error defect after configure door open timeout 255s;

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com