

K1T804 Series Terminal V1.1.3_build190311

Release Note (2019-03-19)

Device Model: DS-K1T804F/MF/EF	Firmware Version	ARM: ACS_1T_EN_GM_V1.1.3_build190311 MCU: Extending_Module_V1.1.2_build181116
	iVMS-4200 Client Version	V2.6.8.9 build20181210

Note: Both ARM and MCU firmware need to be upgraded.

Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Bug Fixed

1. Solve device occasional restart issue when verify fingerprint during device screen off status;
2. Solve the problem of modifying device IP address without entering activation password.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com