

## **KH6 Indoor Station V2.2.42\_build240116 Release Note**

### **(2024-01-29)**

#### **Firmware Basic Information**

<b>Firmware</b>	Firmware Version	V2.2.42_build240116
<b>Basic Information</b>	Device Type	DS-KH6000-E1 (B2) DS-KH6100-E1 (B2) DS-KH6110-WE1 (B1Pro)

#### **Reason of Upgrade**

Add new feature, fix bugs, enhance products quality and meet customers' requirements.

#### **Modified Features**

1. Solve the problem that the doorbell alarm trigger cannot take effect until the device is not activated
2. Fixed: When using some brand standard SIP servers, there is no video when the door station calls the indoor station through standard SIP
3. Fixed the issue that there is a small probability that the wifi hotspot cannot be scanned
4. Optimized the logic of associating the wizard with activated door station
5. Fixed the issue that when the outer door station called the indoor station, there was no lock button or there was a lock button but the unlocking failed in hik-connect app.

## **KH6 Indoor Station V2.2.34\_build231127 Release Note**

### **(2023-11-30)**

#### **Firmware Basic Information**

<b>Firmware</b>	Firmware Version	V2.2.34_build231127
<b>Basic Information</b>	Device Type	DS-KH6000-E1 (B2) DS-KH6100-E1 (B2) DS-KH6110-WE1 (B1Pro)

<b>ivms-4200</b>	ivms-4200 Client	V3.10.1.7 or later
------------------	------------------	--------------------

**Reason of Upgrade**

Add new feature, fix bugs, enhance products quality and meet customers' requirements.

**New Features**

1. Add 4 alarm input function. support arm and disarm the input (with new hardware)

**Modified Features**

1. Improved the smoothness of UI menu (for KH6100 and KH6110 only).
2. Fixed the issue that the device could not receive calls in some languages (for example, Russian, Bulgarian, Hungarian, Romanian, Latvian, etc).
3. Fixed some other minor bugs to enhance the stability of the device.


## **KH6 Indoor Station V2.2.30\_build230821 Release Note (2023-08-23)**

**Firmware Basic Information**

<b>Firmware Basic Information</b>	Firmware Version	V2.2.30_build230821
	Device Type	DS-KH6000-E1 (B2) DS-KH6100-E1 (B2) DS-KH6110-WE1 (B1Pro)
<b>ivms-4200</b>	ivms-4200 Client	V3.9.3.3 (not baseline version, contact technical support for link, baseline iVMS will be available in the end of Q3)

**Reason of Upgrade**

New model DS-KH6000-E1, DS-KH6100-E1, DS-KH6110-WE1 indoor station first time released.



DS-KH6000-E1



DS-KH6100-E1




DS-KH6110-WE1

## New Features


### **DS-KH6000-E1**

1. Cost-effective indoor station without screen
2. Convenient for users to customize functions according to their own usage habits by 4 custom touch buttons.



### *Note:*

Setting the custom touch buttons need to use ivms-4200



(ivms-4200 3.9.3.3)

You can select from below operation for 4 customize touch buttons:

**Button 1:** call (management center / indoor station / indoor extension) , call elevator

**Button 2:** call (management center / indoor station / indoor extension), call elevator, open lock (1 / 2)


**Button 3:** call (management center / indoor station / indoor extension) , call elevator

**Button 4:** call (management center / indoor station / indoor extension) , call elevator

- Due to device hardware performance limitation, only 1 main and 8 sub door stations + 1 main and 8 sub doorphones are supported at most.


## DS-KH6100-E1

- 4.3-inch colorful non-touch screen with resolution 480 × 272
- Convenient for users to customize functions according to their own usage habits by 4 custom touch buttons



**Note:**

Setting the custom touch buttons need to use ivms-4200



(ivms-4200 3.9.3.3)

**Button 1: preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator**

**Button 2: preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator, open lock (1 / 2)**

**Button 3: preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator**

**Button 4: preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator**


4. Due to device hardware performance limitation, only 1 main and 8 sub door stations + 1 main and 8 sub doorphones are supported at most.

## DS-KH6110-WE1


1. Easy and quick set-up: user friendly design
2. 4.3-inch colorful touch screen with resolution of 480 × 272
3. Convenient Hik-Connect APP mobile control
4. Convenient for users to customize functions according to their own usage habits by 4 custom touch buttons

**Note:**

Setting the custom touch buttons from local configuration interface of indoor station or ivms-4200 software.



(local configuration interface of indoor station)



(ivms-4200 3.9.3.3)

**Button 1:** preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator

**Button 2:** preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator, open lock (1 / 2)

**Button 3:** preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator

**Button 4:** preview (ipc / outdoor / confirm(doorphone) ), call (management center / indoor station / indoor extension) , call elevator

## **Notice**

We strongly recommend updating the indoor stations to latest baseline firmware

### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

**Note:**

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)