

# 2 Wire HD Video Intercom Solution Release Note (2024-05-15)

| Device Model     | Firmware Version                            |
|------------------|---|
| DS-KD7003EY-IME2 | VIS_OUTDOOR_F2pro_EN_STD_V1.0.3_build240422 |
| DS-KH7300EY-TE2  | VIS_INDOOR_B1pro_EN_STD_V2.2.38_build240305 |
| DS-KH7300EY-WTE2 |   |
| DS-KD-TDM        | VIS_KDDIS_R0_EN_STD_V1.0.2_240223           |
| DS-KD-TDE        |   |

### Reason of Upgrade


Add new features, enhance products quality and meet customers' requirements.

### **New Features**

1. 1 to 1 pairing and binding with security modules DS-K2M061 is supported, by default it's disabled.

### Note:

Only DS-K2M061 V1.0.2\_build240506 or later support.





# 2 Wire HD Video Intercom Solution Release Note (2024-03-12)

| Device Model     | Firmware Version                            |
|------------------|---|
| DS-KD7003EY-IME2 | VIS_OUTDOOR_F2pro_EN_STD_V1.0.3_build240226 |
| DS-KH7300EY-TE2  | VIS_INDOOR_B1pro_EN_STD_V2.2.38_build240305 |
| DS-KH7300EY-WTE2 |   |
| DS-KD-TDM        | VIS_KDDIS_R0_EN_STD_V1.0.2_240223           |
| DS-KD-TDE        |   |

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

- 1. Optimize the audio and video effect of the intercom between the door station and the Hik-Connect APP under the condition of poor network (Wi-Fi of the indoor station)
- 2. Fixed the issue that there is a very small probability that there is no sound (including voice, audio prompt, tamper alarm) from the out door station.

# 2 Wire HD Video Intercom Solution Release Note (2024-02-15)

| Device Model     | Firmware Version                            |
|------------------|---|
| DS-KD7003EY-IME2 | VIS_OUTDOOR_F2pro_EN_STD_V1.0.3_build240204 |
| DS-KH7300EY-TE2  | VIS_INDOOR_B1pro_EN_STD_V2.2.32_build231012 |
| DS-KH7300EY-WTE2 |   |
| DS-KD-TDM        | VIS_KDDIS_R0_EN_STD_V1.0.2_240223           |
| DS-KD-TDE        |   |

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.



### **New Features**


1. Compatible with new fingerprint & card module DS-KD-MFB (with acrylic front panel) and DS-KD-MFB/S (with stainless front panel), support M1 and Desfire card.





*Note*: Only support collecting and issuing fingerprints from the main module's web remote configuration, not support the use of iVMS-4200 to collect the fingerprints.

2. Compatible with new touch display module firmware V1.0.2\_build240223, and we can configure theme from remote configuration-sub module page.



# 2 Wire HD Video Intercom Solution Release Note (2023-12-15)

| Device Model     | Firmware Version                            |
|------------------|---|
| DS-KD7003EY-IME2 | VIS_OUTDOOR_F2pro_EN_STD_V1.0.2_build231208 |




| DS-KH7300EY-TE2  | VIS_INDOOR_B1pro_EN_STD_V2.2.32_build231012 |
|------------------|---|
| DS-KH7300EY-WTE2 |   |
| DS-KD-TDM        | VIS_KDDIS_R0_EN_STD_V1.0.1_231008           |
| DS-KD-TDE        |   |

## Reason of Upgrade


Fix bugs, enhance products quality and meet customers' requirements.

## **Modified Features**

1. Compatible with new released 12 key nametag module DS-KD-K12 and DS-KD-K12/S



2. Update the default button No. (room number) image.



# 2 Wire HD Video Intercom Solution Release Note (2023-10-25)



| Device Model     | Firmware Version                            |
|------------------|---|
| DS-KD7003EY-IME2 | VIS_OUTDOOR_F2pro_EN_STD_V1.0.1_build231019 |
| DS-KH7300EY-TE2  | VIS_INDOOR_B1pro_EN_STD_V2.2.32_build231012 |
| DS-KH7300EY-WTE2 |   |
| DS-KD-TDM        | VIS_KDDIS_R0_EN_STD_V1.0.1_231008           |
| DS-KD-TDE        |   |

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

3. Optimize Italian language translation in mobile phone web interface

# 2 Wire HD Video Intercom Solution Release Note (2023-10-16)

| Firmware Version                            |
|---|
| VIS_OUTDOOR_F2pro_EN_STD_V1.0.1_build231012 |
| VIS_INDOOR_B1pro_EN_STD_V2.2.32_build231012 |
| VIS_KDDIS_R0_EN_STD_V1.0.1_231008           |
|   |

## Reason of Upgrade

Video intercom 2-Wire HD solution first time released.





### **New Features**

### Door Station-KD7003 main module

- Excellent Product Design: HD images and wide viewing angle (Horizontal: 133°, Vertical: 82°) with WDR
- Excellent Product Design: IP65&IK08 protection level, compatible with released sub-modules (DIS is not supported for now)
- Easy to Use: Support mobile web configuration (AP mode)
- Easy to Use: DEC knobs configuration, Plug & play
- Easy to Use: Multiple indicators--Opening door, calling, on call, in use
- Easy to Use: Single and double buttons can be freely adjusted
- Supports two-lock control (lock1 for pulse lock, lock2 for magnetic/door strike/electric bolt)

#### Capacity:

User capacity: 2000

Linked indoor station capacity: Max.99

Sub door station capacity: 16

### **Indoor Station-KH7300**

- Excellent Product Design: 7-inch touch screen with 1024\*600 high resolution
- Excellent Product Design: 3 touch buttons, physically challenged friendly
- Easy to Use: DEC knobs configuration;
- Easy to Use: Plug & play, support different connection topologies
- Easy to Use: Supports Hik-Connect App (model with W only)
- Easy to Use: Multiple indicators--Wi-Fi, power, mute, in use
- Easy to Use: Max. 4 custom virtual buttons
- View live image of door stations



- Support Professional Studio / Trade button function (Open doors automatically)
- Supports Floor Call (trigger alarm input and indoor station will prompt with audio)

For more information about 2 wire HD products, please refer to the QSG and user manual of device on website:

https://www.hikvision.com/en/products/Video-Intercom-Products/2-wire-Series/2-wire-hd/?category=Video+Intercom+&subCategory=2-Wire+Series&series=2+Wire+HD&checkedSubSeries=NONE

### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com