

## Decoder Version Release Notes (2021-12-28)

<b>Device Model:</b> DS-6900UDI(B)	Firmware Version	DECODER_69UD_EN_NEU_2.6.2_211228 DECODER_69UD_EN_STD_2.6.2_211228
---------------------------------------	---------------------	--

### New Function:

No.

### Modified Features

1. Fixed the problem of returning exceptions through web upgrade
2. Solve the problem of adding password storage beginning with s in the web
3. Fixed the problem of split screen switching when the intelligent decoding resources are full
4. Fix the problem of configuration data after HCP local source is used on the video wall.
5. Solve the problem of web local source drag to the video wall and repeated used inside the device

### Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com