

# Axiom Hub

## Version: V1.0.7

### Release Note

### (2020-10-30)

## 1. Firmware Basic Information

<b>Firmware Basic Information</b>	Firmware Version	V1.0.7_build201029
	Web Version	V4.25.1 build 201029

## 2. V1.0.7 Upgrade Note

### 2.1 Added Function:

**1) Support more multiple languages: **Greek****

**2) Panel Support to Add to HPC Gateway Plus Platform:**

HPC Gateway Plus and Wireless Panel connection via Cloud, Gateway can transmit panel events to third-party platforms.

**3) Support 9 Series Indoor Station Arm/Disarm with password:**

After Panel add to the 9 Series Indoor Station via Hik-connect, indoor station support arm/disarm the Panel with password. It will distinguish users based on passwords for message push.

**4) Support Illegal Card Event Upload**


After unregistered cards swiped, panel will record logs and push messages. Add CID Event---illegal card operations Event. Support APP, ISUP protocol, 4200 shows illegal card operation, the detailed parameter will show card number.

**5) Add NEU Version**

According to market request, add multiple languages NEU version firmware.

## 6) Add SIA-DC09 GMT Function

If enabled, the SIA-DC09 Event time to ARC will use (GMT+00:00) London Time. If disabled, the SIA-DC09 Event time to ARC will use Panel time.




## 2. Feature optimization:

### 1) Cellular Data Usage Optimization

Optimized Cellular Date usage, in normal use scenarios where there is no video uploading, no email sending and other large data uploads, the monthly Cellular Data usage drops to less than 40M..

### 2) User Configuration Interface Optimization



### **3. Issue Fixed:**

- 1) Fix the issue of Wifi configuration Occasional connection failure
- 2) Fix the issue of Pstore can't store 7s videos from the panel.
- 3) Fix the issue of Italian voice broadcast (Stay arm and Away arm)

#### **Remarks:**

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)