

Network Video Recorder

Version: V3.4.4 build170526

Release Note

(2017-05-26 External)

Firmware Basic Information	Firmware Version:	V3.4.4 build170526
	SDK Version:	V5.2.6.30_build20170117
	ONVIF Protocol:	V 2.5.0
	IVMS-4200:	V2.03.04.16 build20151102
	Web component:	<u>V 3.0.5.43</u>

Reason of Upgrade

Delete HiDDNS function and add Hik-Connect function on SP/ST/RT/XT series NVR.

Firmware Upgrade

1. [HiDDNS]

Delete HiDDNS and IP Server access. Available DDNS access include DynDns, PeanutHall, NO-IP.

Enable DDNS

DDNS Type:

Server Address:

Domain:

User Name:

Password:

Confirm:

 Save

2. [Hik-connect]

Support Hik-Connect function, please notice only domain name service is supported. Functions like playback, live view and alarm push with Hik-Connect server are not supported

Optimization

[System]

Optimize the stability of 76/77 series NVR.

Supported Product List			
SP/ST/RT/X series	DS-96xxNI-ST	DS-96xxNI-XT	DS-96xxNI-RT
NVR	DS-77xxNI-ST	DS-77xxNI-SP	
	DS-76xxNI-ST	DS-76xxNI-SP	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action. For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.