

The Release Note 3 MP Incident Detection Camera V5.1.6

Firmware	Firmware Version:	V5.1.6 230423
Basic	Encoding Version:	V2.1 build 230407
Information	Web Version:	V5.1.6.46086 build 230413


Reason of Upgrade

Add new features and optimize product performance.




New features

1. Support the country configuration of Serbian license plate recognition;




- 2. The ONVIF protocol supports profiles;
- 3. Add capture schedule function;




4. Add occupied by animal function;






5. Add the associated masked area configuration;




- 6. ANPR adds the upload ADRNO field;
- 7. The current ICR status is displayed during auto switch;






8. Cloud storage support saving 0.0.0.0 IP address;





Modified functions

- 1. Optimize license plate brightness compensation (FBL) logic;
- 2. The configuration of Stopped Vehicle capture is changed from 1-3 to 2-3, and the default number of captures is changed from 1 to 3;



Related product list

8 MP Incident	iDS-TCS800-C/1550/H1(O-STD)	
	iDS-TCS800-CI/1550/H1(O-STD)	
Detection Camera	Camera iDS-TCS807-CIR/1550(O-STD)	
	iDS-TCS807-CR/200m/1550(O-STD)	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above



changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.