

Title:	How to update the firmware of web component	Version:	v1.0	Date:	3/11/2020
Product:	Web component			Page:	1 of 3

How to How to update the firmware of web component


1. uninstall old web component

- 1) you can find the unins000.exe at the route below: C:\Program Files (x86)\Web Components.
- 2) Double click to uninstall the old component, you should close all browsers first.

名称	修改日期	类型	大小
AudioIntercom.dll	2019/7/11 15:58	应用程序扩展	620 KB
AudioRender.dll	2019/7/11 15:58	应用程序扩展	138 KB
EagleEyeRender.dll	2019/7/11 15:58	应用程序扩展	401 KB
HWDecode.dll	2019/7/11 15:58	应用程序扩展	1,294 KB
ISTask.dll	2019/7/11 15:58	应用程序扩展	66 KB
libeay32.dll	2019/7/11 15:58	应用程序扩展	1,245 KB
NetStream.dll	2019/7/11 15:59	应用程序扩展	1,336 KB
npWebVideoPlugin.dll	2019/7/11 15:59	应用程序扩展	609 KB
OpenAL32.dll	2019/7/11 15:58	应用程序扩展	533 KB
PlayCtrl.dll	2019/7/11 15:58	应用程序扩展	4,315 KB
ssleay32.dll	2019/7/11 15:58	应用程序扩展	285 KB
StreamTransClient.dll	2019/7/11 15:58	应用程序扩展	632 KB
SuperRender.dll	2019/7/11 15:58	应用程序扩展	1,123 KB
SystemTransform.dll	2019/7/11 15:58	应用程序扩展	740 KB
unins000.dat	2019/11/4 10:41	DAT 文件	7 KB
unins000	2019/11/4 10:41	应用程序	687 KB
WebVideoActiveX.ocx	2019/7/11 15:59	ActiveX 控件	543 KB


2. Install new web component

- 1) Log in the device's IP address in IE, and click to download and install the new plug-in.



Title:	How to update the firmware of web component	Version:	v1.0	Date:	3/11/2020
Product:	Web component			Page:	2 of 3

- 2) After installation, re-login the device website, and you can check the plug-in information as below in “Manage Add-In”.





Title:	How to update the firmware of web component	Version:	v1.0	Date:	3/11/2020
Product:	Web component			Page:	3 of 3

First Choice for Security Professionals
***HIKVISION* Technical Support**