

## **I Series NVR V3.3.7 Release Notes**



Reference NO:	20151106_01	
Product	76/77/9676/77/96NI-I series NVR	
Classification:		
Date of	November 2, 2015	
Publication:		
Date of	November 2, 2015	
Change:		

## **Reason of Upgrade**

Add new functions and fix bugs for better performances on 76/77/96NI-I series NVR.

Firmware version*	V3.3.7 build151102			
Special version	None			
Products	76/77/96NI-I series NVR			
Associated module version	SYS -1	Web	V3.0.5.43 build151013	
	SYS -2	SDK	V5.1.3.26_build20150923	
	SYS -3	client	v2.3.4.15 build20151026	
New	NEW_1	RAID 6	DS-9632/64NI-I8 support RAID 6 function	
function	NEW_2	Switch to sub-stream for live view according to resolution	The rule is set for multi-screen (4/6/8 screen) live view which uses main-stream.  1, If the resolution of the first channel live view is higher than 400w, NVR automatically switches to sub-stream for live view.  2, The standard is W*H >400W ( 2048*2048 ) .	
	NEW_3	36/64split screen	Support 36/64 split screen live view	
	SOLVE_1	Network	Email isn't compatible with TLS protocol	



BUG solved	SOLVE_2	Playback	Can't capture in playback
	SOLVE_3	Storage	NAS crashes under continuous searches
	SOLVE_4	Kernel	Problem of I2 series NVR's IR control
	SOLVE_5	Storage	Face detection might cause abnormal restart
Problem remained	Delay_1	Heat Map	Heat map can't be exported to NTFS format storage
			device
	Delay_2	Backup	There's a chance NVR doesn't recognize 3.0 U-disk

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action. For questions or concerns, please contact our local technical support team.

## Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com