

# **I Series NVR V3.3.9 Release Notes**



Reference NO:	20160104_01	
Product	76/77/96NI-I series NVR	
Classification:	70/77/30INI-I Selles INVK	
Date of	December 28, 2015	
Publication:		
Date of	December 28, 2015	
Change:		


## **Reason of Upgrade**

Fix bug for better performances on 76/77/96NI-I series NVR.

# **Firmware Upgrade**

## **Bug Fixed**

i. After setting DDNS area to a country, area/country can't be modified to **Customer**.



# **Related Product list**

	DS-7600NI-I2	DS-7600NI-I2/8P(16P)
-I series NVR	DS-7700NI-I4	DS-7700NI-I4/16P
	DS-9632/64NI-I8	DS-9632/64NI-I16



## **Firmware version**

V3.3.9 build151228

## **Related module version**

Web	V3.0.5.43 build151222
SDK	V5.1.5.11_build20151222
Client	v2.3.6.5 build20151223

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com