

PanoVu Mini Series PTZ Camera V5.4.10

Release Note


Firmware Basic Information	Firmware Version:	V5.4.10 build 180122
	SDK Version:	V5.3.2.5_build20171026
	Play Library (PlayCtrl.dll)	V7.3.3.64_Build20170815
	Encapsulation Library (SystemTransform.dll)	V2.5.1.9
	Voice intercom library	1.3.0.5
	iVMS-4200	V2.6.5.4Build20171114
	IE Client version	V4.0.1 build 171117

1. Compatibility Update


- 1) HIKCGI version: V2.0;**
- 2) ONVIF version: 2.4;**
- 3) ISAPI version: 2.4;**
- 4) Avigilon Control Center: V5.10.12.2(also support V6.x)**
- 5) ExcaqVision: V8.4.2.111542**
- 6) Milestone:**
 - 1) Milestone Enterprise 8.1a(2016 R2 10.2a), Milestone drive version (Device Pack 9.1).
 - 2) Milestone Corporate version(7.0d), Milestone drive version (Driver 9.1).

2. Newly added (Compared V5.4.9)

- 1) Live View interface, Video/audio interface, Image interface, Record interface and Playback interface all support four channels.**




2) Newly add sub stream function, which is mutually exclusive with Capture function, and enabled by default



3) Panorama Linkage function of DS-2PT5326IZ-DE supports auto calibration and the panorama lens position can be adjusted; DS-2PT3326IZ-DE3 and DS-2PT3122IZ-DE3 not support Panorama

Linkage function.



4) Use new Serial No. rules, which support combination of letters and numbers

3. Delete

None

4. Supported Model List

Supported Model List (DS-2PTxxxxx)

DS-2PT5326IZ-DE	DS-2PT3326IZ-DE3	DS-2PT3122IZ-DE3
-----------------	------------------	------------------

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com