

Turbo HD DVR V3.4.91_Build170405 Release Notes (2017-05-18)


	Firmware Version:	V3.4.91_Build170405
	SDK Version:	V5.2.5.40_build20161102
Firmware	Play Library (PlayCtrl.dll)	6.2.0.3
Basic Information	player	7.3.0.74
	Web version	V4.0.1 build161019
	Client version	V2.5.4.1 build20161121

Reason of Upgrade

This version is only suitable for DS-7204/08HUHI-F1/S, DS-7204/08/16HUHI-F2/S. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Modified functions

i. Fix the issue that Hik-connect function can't be enabled by web side.





Related product list:

	DS-7204HUHI-F1/S、DS-7208HUHI-F1/S、
	DS-7204HUHI-F2/S、DS-7208HUHI-F2/S、DS-7216HUHI-F2/S
-F/S Series Turbo	
HD DVR	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com