

# Turbo HD DVR V3.5.25 Build170918 Release Notes (2017-09-22)

	Firmware Version:	V3.5.25 Build170918
	SDK Version:	V5.2.7.30 build20170428
Firmware	Play Library (PlayCtrl.dll)	7.3.2.0
Basic Information	player	4.8mini
	Web version	V4.0.1 build 170419
	Client version	V2.5.8.101 build20170426

# **Reason of Upgrade**

Release Turbo 4.0 DVR new models: DS-7304HUHI-K4、DS-7308HUHI-K4、DS-7316HUHI-K4、DS-9008HUHI-K8、DS-9016HUHI-K8. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

### **Main Features**

- i. Newly release models: DS-7304HUHI-K4、DS-7308HUHI-K4、DS-7316HUHI-K4、DS-9008HUHI-K8、DS-9016HUHI-K8.
- ii. DS-7304HUHI-K4, DS-7308HUHI-K4, DS-7316HUHI-K4, DS-9008HUHI-K8, DS-9016HUHI-K8 support all channels recording 5MP@12fps, 4MP @15fps, 3MP @18fps, 1080P@real-time.
- iii. DS-7300HUHI-K4 supports up to 8MP IPC access.DS-9000HUHI-K4 supports up to 12MP IPC access.
- iv. Newly supports capture function on playback.



## **Related product list:**

1	DS-7104HQHI-K1、DS-7108HQHI-K1、DS-7116HQHI-K1
K Series Turbo HD	DS-7304HUHI-K4、DS-7308HUHI-K4、DS-7316HUHI-K4
DVR	DS-9008HUHI-K8、DS-9016HUHI-K8
1	

### **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com