

## Turbo HD DVR V4.51.001 build 230620 Release Notes

<b>Firmware</b>  <b>Basic Information</b>  V4.51.001 build  230620	Firmware Version:	V4.51.001 build 230620
	SDK Version:	V6.1.9.35
	Player library:	V7.4.0.56
	Web version:	V4.5.0build230509

### **Reason of Upgrade**

- Add some new functions, modify some functions, and enhance product quality to meet customers' requirements.

### **Main update**

#### **i. 【Support motion 2.0 for analog channels】**

All products in the Mapping table support Motion 2.0 for all channels.

#### **ii. 【Improved IP channel access capability】**

The default IP channel number supported by iDS-7316HQHI-M4/S and iDS-8116HQHI-M8/S has been increased from 4 to 8 channels

#### **iii. 【Support perimeter function for analog channels】**

The devices of 16HQHI, 32HQHI, 16HUHI, and 32HUHI models respectively support intelligent perimeter functions for 4, 8, 8, and 16 analog channels

### **Available Modes:**

300228350	iDS-9032HUHI-M8/S(中性)
300228349	iDS-9016HUHI-M8/S(中性)
300228348	iDS-7332HUHI-M4/S(中性)
300228347	iDS-7316HUHI-M4/S(中性)
300228346	iDS-9032HQHI-M8/S(中性)
300228345	iDS-7332HQHI-M4/S(中性)
300228317	iDS-9016HUHI-M8/S(标配)

300228315	iDS-7316HUHI-M4/S(标配)
300228296	iDS-9032HQHI-M8/S(标配)
300228295	iDS-7332HQHI-M4/S(标配)
300228226	iDS-9032HUHI-M8/S(标配)
300228225	iDS-7332HUHI-M4/S(标配)
300228079	iDS-7316HQHI-M4/S(中性)
300228078	iDS-7316HQHI-M4/S(标配)
300228072	iDS-8116HQHI-M8/S(中性)
300228070	iDS-8116HQHI-M8/S(标配)

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com