

AX PRO

Version: V1.2.9

Release Note

(2024-05-16)

1. Firmware Basic Information

Firmware Basic Information	Firmware Version	V1.2.9_build240516
	Device Type	DS-PWA48-E-WB DS-PWA64-L-WE/WB DS-PWA96-M-WE/WB DS-PWA96-M2-WE/WB DS-PWA96-M2H-WE/WB

Notes:

1. Please update firmware to the latest version to ensure the perfect user experience.
2. For installers, it is recommended to install and maintain devices via Hik-Partnerpro.

2. V1.2.9 Upgrade Note


2.1 We optimize the following devices with better power consumption performance.

The related devices list as below:

Model	Firmware recommend to use
DS-PDP15P-EG2-WB(B)	V1.4.5
DS-PDP15P-EG2-WE(B)	V1.4.5
DS-PDC15-EG2-WB(B)	V1.4.5
DS-PDC15-EG2-WE(B)	V1.4.5
DS-PDMC-EG2-WB(B)	V1.4.5
DS-PDMC-EG2-WE(B)	V1.4.5
DS-PDMCK-EG2-WB(B)	V1.4.4
DS-PDMCK-EG2-WE(B)	V1.4.4
DS-PT1-WB(B)	V1.4.3
DS-PT1-WE(B)	V1.4.3

For better performance, customer is recommend to upgrade the control panel to v1.2.9 build20240516 first, and then check new firmware at “Panel Setting → Maintenance → Detector & Peripheral Upgrade” to upgrade the detectors and peripherals

Here are the upgrade instructions:



Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com