

**Axiom Hub**  
**Version: V1.0.5 build191212**  
**Release Note**  
**(2020-01-06)**

## 1. Firmware Basic Information

<b>Firmware Basic Information</b>	Firmware Version	V1.0.5_build191212
	Web Version	V4.25.1 build 191212

## 2. V1.0.5 build191212 Upgrade Note

### 2. Feature optimization:

**1) User name Changed:**

Change the user name from asmministratore to admin.

**2) Keyfob Emergency button Optimization:**

Change the keyfob emergency button function, from No-Voice alarm to voice alarm.  
hold on the button for 2s, it will trigger the siren, and keyboard alarm.



**3) Relay function Optimization:**

Change the relay output time to 1~600s

### 3. Issue Fixed:

- 1) Fix the issue of Wireless PIR Detector need 5 minutes to wake up when armed after adding the wireless keyboard, wireless card reader, wireless siren, and wireless PIR to the Wireless Panel. Now it will wake up immediately.
- 2) Fix the issue of Wireless siren triggered slow (about 4s) after adding the keyboard, card reader, siren, and PIR to the Wireless Panel
- 3) Fix the issue of Chime function will be muted when Chime and Silent Alarm function all enabled.

