

PTZ/Network Camera Firmware Version: V5.7.2

Release Note

(2022-01-07)

Firmware		
Basic Information	Firmware Version:	IPDE_E7_5.7.2build211009

Camera Features

1. New Features

• <u>Newly release the below models:</u>

DS-2DE3A404IW-DE(O-STD)(S6)
DS-2DE3A404IW-DE(O-NEU)(S6)
DS-2DE3A404IW-DE/W(O-STD)(S6)
DS-2DE3A404IW-DE/W(O-NEU)(S6)
DS-2DY3220IW-DE(O-STD)(S6)
DS-2DY3220IW-DE(O-NEU)(S6)
DS-2DY3220IW-DE4(O-STD)(S6)
DS-2DY3220IW-DE4(O-NEU)(S6)
DS-2DY3420IW-DE(0-STD)(S6)
DS-2DY3420IW-DE(O-NEU)(S6)
DS-2DY3420IW-DE4 (0-STD) (S6)
DS-2DY3420IW-DE4(0-NEU)(S6)

2. Improved Features

1) <u>Support flashing & audible alarm for DE3A in released models.</u>

3. Leftover Issues

• <u>N/A</u>



Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the

Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998