

# H8\_V5.8.5 Release Note

## (2023-07-16)

<b>Firmware Basic Information</b>	Firmware Version: V5.8.5 build230530
---	--------------------------------------

### Features

#### New function

- Added smart pan-tilt correction models
- Fixed bugs

### Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

#### ***Remarks:***

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
 No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
 China  
 Tel: +86-571-8807-5998  
 FAX: +86-571-8993-5635  
 Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)

<b>Supported models</b>		
<b>Product series</b>	<b>Smart Pan-Tilt Correction</b>	<b>Product models</b>
PTZ Cameras	Y	DS-2DF8A442IXG-F/SP
PTZ Cameras	Y	DS-2DF8A442IXG-EL
PTZ Cameras	Y	DS-2DF8A442IXG-ELY
PTZ Cameras	Y	DS-2DF8A842IXG-EL
PTZ Cameras	Y	DS-2DF8A442NXG-EL
PTZ Cameras	N/A	DS-2DF8442IXG-ELY
PTZ Cameras	N/A	DS-2DF8442IXG-ELWY
PTZ Cameras	N/A	DS-2DF8442IXG-ELW
PTZ Cameras	N/A	DS-2DF8442IXG-EL
PTZ Cameras	N/A	DS-2DF8C442IXG-EL
PTZ Cameras	N/A	DS-2DF8242IXG-ELW
PTZ Cameras	N/A	DS-2DF8242IXG-EL
PTZ Cameras	N/A	DS-2DF8242I5XG-ELW
PTZ Cameras	N/A	DS-2DF6A436XG-ELY
PTZ Cameras	N/A	DS-2DF6A436XG-EL

PTZ Cameras

N/A

DS-2DF8C442IXG-ELW