

## Turbo HD DVR V3.5.25 build170803 Release Notes (2017-08-15)

<b>Firmware Basic Information</b>	Firmware Version:	V3.5.25 build170803
	SDK Version:	V5.2.7.30 build20170428
	Play Library (PlayCtrl.dll)	7.3.2.0
	player	4.8mini
	Web version	V4.0.1 build 170419
	Client version	V2.5.8.101 build20170426

### **Reason of Upgrade**

Release Turbo 4.0 DVR new models: DS-7104HQHI-K1、DS-7116HQHI-K1. This version is only suitable for DS-7104/16HQHI-K1 series. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

### **Main Features**

- i. Newly release models: DS-7104HQHI-K1、DS-7116HQHI-K1.
- ii. DS-7104HQHI-K1、DS-7116HQHI-K1 support recording 3MP@15fps(part channels like 1st,1st&2nd&3rd and4th), all channels 2MP@15fps, 720P@25/30fps.
- iii. DS-7104HQHI-K1 supports up to 1-ch 4MP IPC access.  
DS-7116HQHI-K1 supports up to 2-ch 4MP IPC access.

**Related product list:**

K Series Turbo HD DVR	DS-7104HQHI-K1、DS-7116HQHI-K1
--------------------------	-------------------------------

**Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

**Note:**

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com