



EUROPEAN TECHNICAL CENTER

FIRMWARE RELEASE NOTE

DS-KB260X Network Access Controller V2.0.4 Build 180706 Release Notes

Device Model: DS-K2601 DS-K2602 DS-K2604	Firmware Version:	V2.0.4 Build 180706
	SDK Version	HCNetSDKV5.3.1.35_build20170911_win32
	Ehome Version	EhomeSDK_V1.2.0.7_build20170712
	Client version	V2.6.5.5 build20171016

Reason of Upgrade

Added or modified functions, enhance products quality and meet customers' requirements

Bug Fixes

1. Fixed a bug where armed zones will become disarmed when the device is rebooted.
2. Fixed a bug where in multiple authentication mode, **super password** event is missing.
3. Fixed a bug where in multiple authentication mode, **input wrong password** event is missing.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you for the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.



Note:

Hikvision has all rights to alter, modify and cancel this notice.

Hikvision doesn't give any guarantee for old models' stock.

Hikvision is not liable for any typing or printing errors.

For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou
310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635