

DS-K1T341C Series Minmoe Terminal Release Notes (2023-06-14)

Device Model: DS-K1T341CM DS-K1T341CMW DS-K1T341CMF DS-K1T341CMFW Naming Rule: M for M1 card, F for fingerprint, W for Wi-Fi	Firmware Version	ACS_641A_F1plus_EN_STD_V3.3.8_build230330 ACS_641A_F1plus_EN_NEU_V3.3.8_build230330
	SDK	Latest baseline version
	iVMS-4200 Version	Latest baseline version

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

DS-K1T341C Series Minmoe Terminal Release Notes (2022-07-01)

Device Model: DS-K1T341CM DS-K1T341CMW DS-K1T341CMF DS-K1T341CMFW Naming Rule: M for M1 card, F for fingerprint, W for Wi-Fi	Firmware Version	ACS_641A_F1plus_EN_STD_V3.3.8_build220610 ACS_641A_F1plus_EN_NEU_V3.3.8_build220610
	SDK	Latest baseline version
	iVMS-4200 Version	Latest baseline version

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

1. Fixed some ISAPI protocol integration issues
2. Optimize the synchronization logic of personnel permissions

3. Modify the problem of abnormal ISUP parameter configuration
4. Optimize the camera preview effect

DS-K1T341C Series Minmoe Terminal Release Notes (2022-06-08)

Device Model: DS-K1T341CM DS-K1T341CMW DS-K1T341CMF DS-K1T341CMFW Naming Rule: M for M1 card, F for fingerprint, W for Wi-Fi	Firmware Version	ACS_641A_F1plus_EN_STD_V3.3.8_build220531 ACS_641A_F1plus_EN_NEU_V3.3.8_build220531
	SDK	Latest baseline version
	iVMS-4200 Version	Latest baseline version

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

1. Optimized Bluetooth automated test solution

DS-K1T341C Series Minmoe Terminal Release Notes (2022-04-18)

Device Model: DS-K1T341CM DS-K1T341CMW DS-K1T341CMF DS-K1T341CMFW Naming Rule: M for M1 card, F for fingerprint, W for Wi-Fi	Firmware Version	ACS_641A_F1plus_EN_STD_V3.3.8_build220418 ACS_641A_F1plus_EN_NEU_V3.3.8_build220418
	SDK	Latest baseline version
	iVMS-4200 Version	Latest baseline version

Reason of Upgrade

New model DS-K1T341C series face recognition terminals first time released.




New Features

1. 4.3 inch capacitive touch screen, 2 MP wide-angle dual-lens camera with WDR feature;
2. Connect external card reader or access controller via RS485 or Wiegand26/34 protocol
3. Face recognition duration < 0.2 s/User; face recognition accuracy rate $\geq 99\%$

4. Face, card, fingerprint, event capacity

	Face	Card (M1)	Fingerprint	Wi-Fi	Event
DS-K1T341CM	3,000	3,000	×	×	150,000
DS-K1T341CMW	3,000	3,000	×	✓	150,000
DS-K1T341CMF	3,000	3,000	3,000	×	150,000
DS-K1T341CMFW	3,000	3,000	3,000	✓	150,000

5. Multiple language: English, Español, العربية, русский, ภาษาไทย, Bahasa Indonesia, Português Brasileiro, Tiếng Việt, 한국어
6. ISAPI protocol makes it easier for integration with third-party;
7. Remote video intercom and unlock door from Hik-Connect App on your mobile/Pad
8. Support ISUP 5.0(EHome 5.0) protocol to manage devices in different location;
9. Self-defined shortcut key (QR Code, Call and Password) on main interface;
10. Login and configure device in **web client** via browser;
11. Self-defined voice prompt (TTS function, English only) and screen display info(user ID, name and face picture) for verification;



12. Network

Support TCP/IP, adapt to LAN(network) or WAN(ISUP 5.0) network environment

13. Function

- a. Two-way audio with client software, door station, indoor station, and main station
- b. Multiple verification modes: Face, card, fingerprint(DS-K1T341CMF/CMFW only) and QR code;
- c. Supports face mask detection
- d. Support check in/check out/break out/break in/overtime in/overtime out status;
- e. Optional fingerprint recognition module(model with F)
- f. Support custom standby background image
- g. IP65 protection level
- h. Supports face recognition in low illumination
- i. Supports live view on the platform, H.264

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com