

## 69 series decoder

Version: V2.5.0

## Release Note

(2020-05-27)

<b>Firmware</b> <b>Basic Information</b>	Firmware Version:	V2.5.0
	Decoding Version:	V2.5
	Web Version:	V4.1.1
	Plugin Version:	V3.0.5.40

### Reason of Upgrade

Change the master control chip.

Support export abnormal information to PC.

### Firmware Upgrade


### New Features

#### 1. [Export abnormal information]

Support export diagnose log to pc on web.

The screenshot shows the Hikvision web interface for the 69 series decoder. The top navigation bar includes 'Video Wall', 'Video Wall Configuration', and 'Configuration'. The left sidebar contains 'System', 'System Settings', 'Maintenance', 'User Management', 'Network', 'Decoding Configuration', and 'Security Control'. The main content area is titled 'Upgrade & Maintenance' and 'Diagnose'. It features four sections: 'Export Captured Packet to USB Device' (Current Status: Default, Packet Capture Command: tcpdump -i eth0 -w /home, Enable button), 'Export Logs to USB Device' (Current Status: Default, Enable button), 'Export Logs from USB to Local' (Export Type: By Time, Start Time: 2020-06-30 00:00:00, End Time: 2020-06-30 23:59:59, export button), and 'Export Auto-Diagnosis Log' (export button). A red box highlights the 'Export Auto-Diagnosis Log' section, and a red arrow points to the 'export' button.

You need to set password to encrypt it.



The image shows a screenshot of a web-based configuration dialog box titled "File encryption configuration". The dialog box has a dark header bar with the title and a close button (X). Below the header, there are two text input fields. The first field is labeled "Please input encrypted p..." and the second field is labeled "Confirm". At the bottom right of the dialog, there are two buttons: "OK" and "Cancel".

### **Note**

1. The device supports to be connected by SSH for remote checking problems. The user name is "root" and the password is the same as admin. After rebooting device, we need to open SSH function on web again.
2. V 1.0.0 – V2.4.0 version cannot upgrade to V2.5.0

### **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.