

Emergency Alarm Firmware

Version: V2.0.5

Release Note

(2020-01-29)

Firmware Basic Information	Firmware Version:	H2_V2.0.5_ 191119
	Firmware Version:	H3_V2.0.5_ 191119
	Firmware Version:	H5_V2.0.6_ 191125
	Firmware Version:	H11_V3.0.1_ 191111
	iVMS-4200	V2.7.4.5



Firmware
Corresponding Li:

1. Upgrade Note

1.1 Panic Alarm Station V2.0.5 Version

Features

1. SIP Protocol Optimization

2. Device Type

Firmware	Product Type	Product Model
HEA_H2_EN_STD_V2.0.5_build191119	Non-Visible Panic Alarm Station	DS-PEA1-N1
HEA_H3_EN_STD_V2.0.5_build191119	Panic Alarm Station	DS-PEA1-21
	Box Panic Alarm Station	DS-PEA2-21
	Pole Panic Alarm Station	DS-PEA3M-21
	Pole Panic Alarm Station	DS-PEA3M-21H

HEA_H5_EN_STD_V2.0.6_build191125	Panic Alarm Master Station	DS-PEA4L-7
HEA_H11_EN_STD_V3.0.1_build191111	Panic Alarm Master Station	DS-PEA4H-10

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com