

iVMS-4200

Version:V2.8.2.2 build190128

Release Notes

(2019-02-25)

General Information

Software Version	V2.8.2.2 build20190128
Network SDK Lib	V5.3.6.42build20190111
Play Lib	V7.3.6.61build20181010
VCA Config Lib	V3.4.25.2 build20180228
SADP Lib	V4.2.3.2 build20180124

Video Module

1. Fixed the problem of spelling errors in CloudP2P login interface.
2. Optimized the layout in module customized interface.
3. Fixed translation problem.

Non-video Module

1. Fixed the problem that the USB camera can't be added. (Including device models: DS-2CS5432B-S, DS-2CS54D2B, DS-2CS54D2B-S, DS-2CS-54C2B, DS-2CS54C2B-S).
2. Fixed translation problem in access control alarm event.
3. Fixed the problem that when setting the duress code, super code and dismiss code , only need one digit to save and take affect. Now it needs more than 4 digit to take effect .
4. Fixed the problem that the card for disabled person's card swiping records can't be used as attendance records.
5. Fixed the problem that can't configure door station's Alarm in and Alarm out in access control parameters interface.
6. Fixed the problem that the daily attendance record can't be sent by email.
7. Fixed the problem of identification of some USB cameras.
8. Fixed the problem that the Disable Alarm Output interface will disappear after set linkage on DS-K1T501SF/K1T500S/K1T500SF.
9. Fixed the problem when issuing card with dual frequency card.
10. Fixed the problem that snapshots can't display in status monitor interface.
11. Fixed the language display error in Access control and video intercom wizard.
12. Fixed the crash issue when configure sending regular attendance report mail.
13. Fixed the problem that events can't be searched.

Remote Configuration of Security Control Panel

1. Fixed the translation problem in *subsystem configuration* interface.
2. Fixed the problem of emptying the *subsystem configuration* interface after adding users to *Keyboard User* interface.
3. Fixed the problem that can't view the state of the defense zone in *Alarm Management* interface .
4. Fixed the problem that can not view APN configuration and network connection time in *GPRS reporting* interface.
5. Removed the *Generate output Control* and *Point Alarm Linkage* options in the *Other* interface.

CloudP2P Module

1. Fixed the problem of failing to connect to Russian server.
2. Fixed the crash issue in CloudP2P remote playback module.