

NVR V3.4.1 Release Notes



| | |
|-------------------------|--|
| Reference NO: | 20160108_01 |
| Product Classification: | WIFI NVR, LCD NVR, -G series NVR,-E series NVR and -ST/SP/RT/XT series NVR |
| Date of Publication: | January 7, 2016 |
| Date of Change: | January 7, 2016 |

Reason of Upgrade

Add new functions and fix bugs for better performances on WIFI NVR 22 inch LCD NVR, -E series NVR and -ST/SP/RT/XT series NVR.

Firmware Upgrade

New Features

- [LPR]**
After NVR is accessed to IVMS-5200 platform, users can edit the black/white list of LPR.
- [HiDDNS]**
Add 16 countries' names: Paraguay, Haiti, Netherlands Antilles, El Salvador, Panama, Guatemala, Nicaragua, Honduras, Costa Rica, Aruba, Belize, Cayman Islands, Curacao, Dominican Republic, Martinique, Puerto Rico.
Modify 3 country/area names: Burma-Cambodia, Other Europe-Europe Other, Other America-America Other
- [Live view strategy]**
In multi-screen mode, NVR will automatically switch to sub-stream for live view if the channel's resolution is higher than 2MP.

Bug fixed

- [System]**
NVR might reboot while user enters PTZ interface (Menu-Camera-PTZ).
- [Keyboard]**
Keyboard DS-1005KI can't control PTZ to zoom in and zoom out through NVR.

3. [Event]

If the IP address of NVR is modified when event occurs, NVR can't receive event message from IPC afterwards.

Related Product list

| | | | |
|-----------------|---------------------|-----------------|-----------------|
| Products | 76/77/ E series: | | |
| | DS-76xxNI-E1 | DS-76xxNI-E1/xP | DS-76xxNI-E1/xN |
| | DS-76xxNI-E2 | DS-76xxNI-E2/xP | DS-76xxNI-E2/xN |
| | DS-77xxNI-E4 | DS-77xxNI-E4/xP | |
| | LCD NVR: | | |
| | DS-7600NI-E1/A | | |
| | 76/86/96 ST series: | | |
| | DS-96xxNI-ST | DS-96xxNI-XT | DS-96xxNI-RT |
| | DS-86xxNI-ST | DS-86xxNI-XT | DS-76xxNI-ST |
| | DS-76xxNI-SP | DS-77xxNI-ST | DS-77xxNI-SP |
| | WIFI NVR: | | |
| | DS-7108NI-E1/V/W | | |
| | 76 G series: | | |
| DS-7608NI-G2/4P | | | |

Firmware version

V3.4.1 build151225

Related module version

| | |
|----------|---------------------------|
| Web | V4.0.1 build 151209 |
| SDK | V5.1.3.33_build20151030 |
| Client | V2.03.04.16 build20151102 |
| Protocol | Onvif 2.5.0 |

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com