

Network Video Recorder

Version: V3.4.82 build160818

Release Note

(2016-8-22)

Firmware Basic Information	Firmware Version:	V3.4.82 build160818
	SDK Version:	V5.2.3.15
	ONVIF Protocol:	ONVIF V2.5.0
	IVMS-4200:	V2.4.7.11 build20160715
	Web Component:	V3.0.6.6 build 160714

Reason of Upgrade

Fix bugs and optimize function for better performances on I series NVR.

Optimization

1. [Decoding Capacity]

DS-7608NI-I2 (/8P)'s decoding capacity will decrease by 1-ch 1080P if user customizes CVBS port. Other I series models' decoding capacity won't be affected by CVBS port.

2. [Function Modification]

Delete thermal camera VCA and double-stream recording function on DS-7608NI-I2 (/8P) for more stable performance.

3. [RAID]

Fix the issue that RAID function isn't available on DS-9600NI-I8/16 NVR.



Supported Product List			
	DS-7608NI-I2	DS-7608NI-I2/8P	
I series NVR	DS-7616NI-I2	DS-7616NI-I2/16P	
	DS-77xxNI-I4	DS-77xxNI-I4/16P	
	DS-9632/64NI-I8	DS-9632/64NI-I16	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.