

Turbo HD DVR V3.5.23 Build171109 Release Notes (2017-11-14)


| | | |
|---------------------------------------|-----------------------------|-------------------------|
| Firmware Basic Information | Firmware Version: | V3.5.23 Build171109 |
| | SDK Version: | V5.2.7.30 build20170428 |
| | Play Library (PlayCtrl.dll) | 7.3.3.0 |
| | player | 4.8mini |
| | Web version | V4.0.1 build 170525 |
| | Client version | V2.6.5.6 build 171017 |

Reason of Upgrade

Newly support the combination of letters and numbers as Serial Number, add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Main Features

- i. Newly support the combination of letters and numbers as Serial Number.
- ii. This version newly supports two models DS-7104HQHI-K1 and DS-7116HQHI-K1. Refer to the **Related product list** below for supported models in this version.
- iii. Cancel the restriction that gateway IP and IP address can't be set in the different network segment to meet customers' requirement.



Related product list:

| | |
|--|--|
| K Series Turbo HD DVR | DS-7104HQHI-K1、DS-7108HQHI-K1、DS-7116HQHI-K1 |
| | DS-7204HQHI-K1 |
| | DS-7208HQHI-K1、DS-7208HQHI-K2 |
| | DS-7216HQHI-K1、DS-7216HQHI-K2 |
| | DS-7204HQHI-K1/P、DS-7208HQHI-K2/P、DS-7216HQHI-K2/P |
| | DS-7204HUHI-K1、DS-7204HUHI-K2、DS-7208HUHI-K1、DS-7208HUHI-K2、DS-7216HUHI-K2 |
| | DS-7204HUHI-K1/P、DS-7208HUHI-K2/P |
| DS-7304HQHI-K4、DS-7308HQHI-K4、DS-7316HQHI-K4 | |

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com